

Reclaimed Water Inspection Report

Project/Site Name: Pharmagen
 Proj/Customer ID _____

Prepared By: Edward Digbee
 Date: 10/05/2005

Test For:
 New Construction Retrofit Inspection
 Quadrennial Inspection Modification Inspection
 Annual Inspection Other Inspection

Site Contact: Billybob Bojenkins
 Relationship to Property: Maintenance Supervisor

Water Use:
 Cooling Tower Other
 Dual Plumbing Irrigation

Site Address: 678 W. Main ST
X Broadway

Site Supervisor: Yes No

Meter Address: 888 Gamolucci Court
 Mail Address: 678 Elmwood Circle
San Francisco CA 94107

Number of Meters: _____ Potable _____ Irrigation
 _____ Combo _____ Reclaimed Water

Site Supervisor: Joseph Blauman
 Site Supervisor Training Date: 08/01/2005

Health Dept # _____
 Work Order # _____

Site Supervisor Phone: (415) 258-6985
 Drawing # _____

Inspection Details	Pass	Fail	Notes and Discrepancies	Adherence
Installation Completed				
Clock Hours of Operation				
Signage, Valve, Heads, Warning				
Unauthorized Connections				
Overspray				
Overwatering				
Ponding, Excessive Run-Off				
BFP at Potable Meters				
Controller Map On Site				

Comments: *** 10/09/2005 - 7:21 PM Designer ***

<input type="checkbox"/> Potable Water Shutdown Test Start Date: <u>10/05/2005</u> Time: _____ Completion Date: _____ Time: _____	<input type="checkbox"/> Reclaimed Shutdown Test Start Date: <u>10/05/2005</u> Time: _____ Completion Date: _____ Time: _____
Meter Reading <u>250678160</u>	

Reclaimed Water Program

